



PROJECT PROFILE

PROJECT: Operating Theatre Refurbishment
LOCATION: Spain

THE PROBLEM

The internal walls and ceiling of this operating theatre were in an extremely bad condition.

Due to the condition of the walls and ceiling, the operating theatre had been shut down, resulting in high costs for the customer.

A protection system was required that would allow normal operating procedures to commence as quickly as possible.



THE SOLUTION



Thortex hygienic protection systems were chosen to provide the solution.

Uni-Tech GP Primer was applied to both the walls and ceilings and two coats of Wall-Tech UV in white applied to the ceiling and two coats of Wall-Tech WB in light green applied to the walls.

The operating theatre was able to be put back into service immediately.