



PROJECT PROFILE

PROJECT: Heliport Repair
LOCATION: Germany

THE PROBLEM

This heliport is part of a hospital and it was therefore vital that it remained operational.

The lights and cables around the landing area were in need of replacing. The heliport could only be out of use for a short period and a repair system that would cause minimum disruption was required.



THE SOLUTION



All damaged and loose concrete was removed and channels 20cm wide and 10cm deep were formed in the concrete.

The cables were replaced and the damaged areas were rebuilt with Grano-Tech.

This repair caused minimum disruption and after a few hours, the heliport was back in service.