



PROJECT PROFILE

PROJECT: Hangar Floor Protection
LOCATION: United Kingdom

THE PROBLEM

These photographs show hangar three at Gatwick Airport.

The existing coating was in poor condition and had been badly attacked by skydrol fuel.

The whole hangar floor required protection to improve its condition and also give greater light to the hangar.

The area to be protected totalled 4,700m².



THE SOLUTION



The areas of floor that were most badly damaged were rebuilt with Floor-Tech RS.

The hangar floor was then coated with Floor-Tech SP Primer followed by Floor-Tech HB.

With such a large area involved, the floor was refurbished in sections so that adjoining areas could continue to be used for the ongoing maintenance of British Airways aeroplanes.