



## PROJECT PROFILE

**PROJECT:** Refurbishment of External Plastisol Sheeting  
**LOCATION:** United Kingdom

### THE PROBLEM

This building is a hangar where military aircraft are serviced and maintained. It is therefore vital that it remains in use at all times.

As the photograph shows, the external plastisol sheeting was now degrading badly and in need of immediate refurbishment.



### THE SOLUTION



The entire building was first cleaned to remove all contamination and ensure a sound substrate was left.

All areas where rusting had occurred were first treated with Corro-Tech GP. All exposed metal areas were coated with Uni-Tech MC Primer and the complete hangar was then coated with one coat of Wall-Tech PU.

As is clear from the photograph, the application of Thortex products has completely refurbished the hangar.