



www.thortex.co.uk

PROJECT PROFILE

PROJECT: Hospital Emergency Staircase - Corrosion Protection
LOCATION: Spain

THE PROBLEM

Due to the effects of the environment and time, the external emergency staircase at this hospital was suffering from severe corrosion, as can be seen from the photograph.

The Building Maintenance Manager requested that it must be returned to its original condition.



THE SOLUTION

The corroded areas were suitably prepared and coated with our anti-corrosive epoxy Corro-Tech GP, ideal for the protection of new and existing steel structures where preparation is restricted. Two coats of Uni-Tech UV were then applied.

Uni-Tech UV is a two component, solvent-based polyurethane coating which offers outstanding colour and gloss retention.

The client was pleased with the results.