



## PROJECT PROFILE

**PROJECT:** Fire Escape Stairway

**LOCATION:** Spain

### THE PROBLEM

The fire escape external staircase in this hospital was very badly corroded.

This was creating a safety hazard as well as reflecting badly on the hospital's image.



### THE SOLUTION



It was only possible to manually prepare the fire escape.

After the surface had been manually prepared, one coat of Corro-Tech GP Primer and two coats of Uni-Tech UV in blue were applied.

This has both protected the fire escape and improved its overall appearance.