



## PROJECT PROFILE

**PROJECT:** Hospital Refurbishment  
**LOCATION:** Spain

### THE PROBLEM

The external walls of this hospital building in Spain were a cementitious cladding system. As is apparent from the photograph, these panels had deteriorated badly over a period of time and were severely staining the surface. This was causing contamination to the exterior of the building, including damage to the window frames.

Refurbishment was required to bring this building back up to a good finish, especially as it was a prominent building on the Barcelona sky line.



### THE SOLUTION



The entire external surface of the building was first of all cleaned to remove all dirt. All loose and friable concrete was removed to provide sound surfaces. Any areas that needed rebuilding were first rebuilt with Wall-Tech LW. The entire surface was then protected with the Wall-Tech PU system in white and light grey.

The finish has completely transformed the external appearance of this building. The client is delighted with the finish that has been achieved.